

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ENGLE FARM, BARN
89 South Ebey Road
Coupeville vicinity
Island County
Washington

HABS WA-247-A

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Anne E. Kidd, photographer, April 2006

- | | |
|------------|--|
| WA-247-A-1 | EXTERIOR PERSPECTIVE SHOWING CONNECTION BETWEEN THE HOG BARN AND THE 1954 ADDITION, LOOKING NORTH. (After a fire destroyed the main barn on the property, this addition was hastily added to the north end of the hog barn to provide temporary storage for hay bales. Fifty-four years later, the barn addition is still in use.) |
| WA-247-A-2 | INTERIOR OF THE BARN ADDITION WITH FINK TRUSS SYSTEM, LOOKING EAST. (Straw bales stored in the barn addition, with the north façade of the slaughter house on the right.) |
| WA-247-A-3 | INTERIOR OF HOG BARN SHOWING MILKING STANCHIONS AND DIAGONAL SHEATHING, LOOKING EAST. (In the 1940s the hog barn was converted to a calf barn to service the growing dairy. After a fire on the property took the Engle's main barn in 1954, the building was converted into a milking parlor.) |